

NORTHERN DIVER

Cylinder Inspection and Test Certificate

Job No. 301340

Owner's Name Mr/Mrs/Ms 23 PARA Forename/initials -

Owner's Address ENGR REGT DIVE TEAM, WOODBRIDGE

Post Code IP12 3LU Phone No. -

Make FABER Ser No 05/1763/059 Capacity 12.2 litre

A Periodic Inspection and Hydraulic Test or Visual Inspection only was carried out, in accordance with ASSET CP2 and BS EN 18119 or BS EN 1803 .

Comments

Visual: External condition: Satisfactory Fail

Visual: Internal condition: Satisfactory Fail

Make and identification of valve - - -

Valve maintenance in accordance with BS EN ISO 22434 and BS EN ISO 13341:

Physical condition: Satisfactory Fail

"DIN" outlet threads: N/A Satisfactory Fail

Valve stem threads: Satisfactory Fail

Cylinder neck threads: Satisfactory Fail

Valve: Replaced Y N Refurbished Y N

Eddy current test (Compulsory for AA6351/AA6082 Aluminium) Y N/A Pass Fail

Test unit: Visual Plus Visual Eddy Serial No -

Note: When an eddy current test has been carried out, an additional mark or label is applied adjacent to the required test/inspection marks. This indicates to the filler that an eddy current test has been carried out.

Hydraulic test: N/A (Visual only) Pass Fail

This cylinder is is not fit for another period of use as defined by the above standards.

If passed, the next test/inspection is due on - / - / -

Signed on behalf of the company S. Wilson Date 20 / 01 / 21

Note: Cylinders and/or valves that fail the required inspection or test are retained for destruction as required by the applicable Standards.